

Boundary Forest Watershed Stewardship Society (BFWSS) PO Box 2926 Grand Forks, BC V0H 1H0 www.boundaryforest.org boundaryforest@gmail.com

Honourable George Heyman, Minister of Environment and Climate Change Strategy Honourable Doug Donaldson, Minister of Forests, Lands, Natural Resource Operations and Rural Development Parliament Buildings Victoria, BC

August 9, 2019

Dear Ministers Donaldson and Heyman,

## **RE: GRANBY BLUEJOINT L/O FOREST SERVICE ROAD**

The Granby Bluejoint FSR was recently inspected by BFWSS.

This road was recently brushed and graded. Much debris exists in ditches and culverts are fouled. The road lacks crown. The approaches to the bridge at about 2.2 km need brushing.

The newly constructed road leading toward the Granby Park Trail has been built without crown. While water control measures seem adequate at present, the lack of crown will inevitably create future problems.

It was noticed that cut block boundary ribbons have been placed along the road edge adjacent to a stand of healthy immature Larch. It is assumed that harvesting here will take place soon – 100 years before culmination age.

Authorized by:

Boundary Forest Watershed Stewardship Society Board of Directors